

FIG. 1






Takahisa TANAKA
Threading Control Method and Apparatus Therefor Q86219
April 15, 2005
(202) 2937060
Sheet 3 of \$\mathred{S}\$

3/8

FIG. 3




F⊿Ts :MAIN-SPINDLE MOVEMENT AMOUNT PER CONTROL CYCLE F⊿Tsc:POST-CORRECTION MAIN-SPINDLE MOVEMENT AMOUNT PER CONTROL CYCLE


F⊿Tz:THREADING-SPINDLE MOVEMENT AMOUNT PER CONTROL CYCLE F⊿To:THREADING-SPINDLE MOVEMENT AMOUNT AT FIRST INTERPOLATION


F_Tn:THREADING-SPINDLE MOVEMENT AMOUNT AT SECOND AND SUBSEQUENT INTERPOLATIONS

F⊿TI:THREADING-SPINDLE MOVEMENT AMOUNT AT FINAL INTERPOLATION ⊿T:CONTROL CYCLE

FIG. 4







 ${\it FZTo}$: THREADING-SPINDLE MOVEMENT AMOUNT AT FIRST INTERPOLATION F ${\it LTn}$: THREADING-SPINDLE MOVEMENT AMOUNT AT SECOND AND SUBSEQUENT INTERPOLATIONS AT: CONTROL CYCLE <u>/</u>Pn + P)

✓Po: FIRST MAIN-SPINDLE POSITION CHANGE AMOUNT (NUMBER OF PULSES)
 ✓Pn: SECOND AND SUBSEQUENT MAIN-SPINDLE POSITION CHANGE AMOUNTS (NUMBER OF PULSES)
 P: NUMBER OF PULSES PER SINGLE MAIN-SPINDLE ROTATION

L: THREAD LEAD

FIG. 7

